

Several activities are initiated. Waiting for Pressure acknowledgements. Due to a Timer missing acknowledgement leads to return to the Idle state.

Starting	Entry action	MyCmd_Clear SetPressure_Set Counter_ResetStart Timer_ResetStart Ofun_CalcLimit
	eXit action	Timer_Stop
	RequiredPress_CHANGED	Timer_ResetStart
	Pump_TooHot	AI_PumpTooHot
	Timer_OVER	AI_PressureError
Regulating	Press_OK	
Idle	Pump_TooHot Timer_OVER	