

This is a final state where everything works as required: the pressure in the two chambers controlled by the Pressure slaves is ok and the Device slave is running.
Disturbances in the slaves or the command Stop cause the state machine to go to the state Stop.

On	Entry action	
	eXit action	
Stop	Cmd_Stop Device_Error Pressure1_Idle Pressure2_Idle	